

CC1 Site Assessment Survey

Date 7/7/15 Time 12:00

Site Assessor Unawep WFM

Site Type

- Cabin**
 Allotment
 Camp
 RAWS
 Historical
 Homestead
 Construction
 Archeological
 Communications
 Mining
 Camp
 Trade&Mfg
 Allotment
 T&ESpecies
 Mech.Equip.
 Headquarters
 Other

Quad Name _____ Lat 64 19.828' TWN/RNG/SEC _____
 Quad _____ Long 146 56.905' Allotment #42
 Number _____
 Owner Kurt and Carl Lindig Phone 907-460-1971 Permit # _____
 Address 5 Mile Clear Creek

Description of Location

First structure on 5 Mile Clear Creek on river right (looking down river).

3 total structures on site, main cabin, storage shed, outhouse.

Wood construction.

Fire Management Option (Site Protection Level)

- Limited
 Full
 Modified
 Critical
 Avoid
 Non-sensitive
 Pending determination

Land Status

- BLM
 NPS
 State
 Trespass
 FWS
 USFS
 Military
 Private
 Native Corporation

Cabin Description

- | | | | | |
|--|---|---|--|---|
| Cabin Construction
<input type="checkbox"/> Log
<input checked="" type="checkbox"/> Frame
<input type="checkbox"/> Other
<u>3</u> # of outbuildings | Foundation
<input type="checkbox"/> Closed
<input type="checkbox"/> Open
<input checked="" type="checkbox"/> Deck
<input type="checkbox"/> Other | Roof Type
<input checked="" type="checkbox"/> Metal
<input type="checkbox"/> Shake
<input type="checkbox"/> Composite
<input type="checkbox"/> Sod
<input type="checkbox"/> Blue tarp | Condition of Cabin
<input checked="" type="checkbox"/> Complete structure
<input type="checkbox"/> Walls without roof
<input type="checkbox"/> Under construction
<input type="checkbox"/> Walls & roof collapsed
<input type="checkbox"/> Cabin site, remains | Hazardous Materials
<input type="checkbox"/> None
<input type="checkbox"/> Empty fuel cans
<input checked="" type="checkbox"/> Full fuel cans
<input type="checkbox"/> Batteries
<input checked="" type="checkbox"/> Other |
|--|---|---|--|---|

Description (outbuildings, docks, machinery, defensible space, etc.)

3 Total structures on site accessible by boat. Open deck facing the creek. Black Spruce has been thinned by 1 chain around the main structure. Two sprinkler kits have been set up, ran by 1 mark 3.

Over-story

- White Spruce
 Black Spruce
 Mixed
 _____ % Hardwoods
 _____ % Conifer

Average Tree Height

_____ Spruce 30ft
 _____ Hardwood

Vegetation/Fuel Inventory

Understory

- Tall Shrub >6 ft
 Short Shrub <6 ft
 Grass/Forbes
 Moss/Lichens

Canopy Closure

- Closed >50%**
 Open 10-49%

Ladder Fuels

- Yes**
 No

Fuels Description

Terrain

Slope

- 0-25%**
 51-75%
 26-50%
 76-100%

Aspect

- N
 E
 S
 W
 NE
 SE
 SW
 NW
 Flat

Suppression Data

Water Source

Location/Description 5 Mile Clear Creek

Helispot

Location/Description 64 19.578', 146 55.838'

Other Access

Location/Description Jet, or airboat access only from Salcha boat launch. Salcha River to Tanana to 5 MI Clear Creek.

Notes:

Inhabited

Photo included

Sketch of plumbing set up on back



CC2 Site Assessment Survey

Date 7/7/15 Time 12:00

Site Assessor Unawweep WFM

Site Type

- Cabin, Allotment, Camp, RAWS, Historical, Homestead, Construction, Archeological, Communications, Mining, Camp, Trade&Mfg, Allotment, T&ESpecies, Mech.Equip., Headquarters, Other

Quad Name, Lat, TWN/RNG/SEC, Quad, Long, Allotment #40, Owner, Linda Gavin, Phone, Permit #, Address, 5 Mile Clear Creek

Description of Location

Second structure on 5 Mile Clear Creek on river left (looking down river).

2 total structures on site, Quonset hut, green house.

Metal construction with plastic sheeting.

Fire Management Option (Site Protection Level)

- Limited, Modified, Avoid, Pending determination, Full, Critical, Non-sensitive

Land Status

- BLM, FWS, Native Corporation, NPS, USFS, State, Military, Trespass, Private

Cabin Description

- Cabin Construction: Log, Frame, Other; Foundation: Closed, Open, Deck, Other; Roof Type: Metal, Shake, Composite, Sod, Tarp; Condition of Cabin: Complete structure, Walls without roof, Under construction, Walls & roof collapsed, Cabin site, remains; Hazardous Materials: None, Empty fuel cans, Full fuel cans, Batteries, Other

Description (outbuildings, docks, machinery, defensible space, etc.)

2 Total structures on site accessible by boat. Black Spruce has been thinned by 1 chain around the main structure. One sprinkler kit has been set up, ran by 1 Shindaiwa.

Vegetation/Fuel Inventory

- Over-story: White Spruce, Black Spruce, Mixed; Average Tree Height: Spruce 30ft, Hardwood; Understory: Tall Shrub >6 ft, Short Shrub <6 ft, Grass/Forbes, Moss/Lichens; Canopy Closure: Closed >50%, Open 10-49%; Ladder Fuels: Yes, No

Fuels Description

- Slope: 0-25%, 51-75%, 26-50%, 76-100%

Terrain

- Aspect: N, E, S, W, NE, SE, SW, NW, Flat

Suppression Data

- Water Source: 5 Mile Clear Creek; Helispot: 64 19.578', 146 55.838'; Other Access: Jet, or airboat access only from Salcha boat launch. Sacha River to Tanana to 5 MI Clear Creek.

Notes:

- Uninhabited, Photo included, Sketch of plumbing set up on back



CC3 Site Assessment Survey

Date 7/7/15 Time 12:00

Site Assessor Unawweep WFM

Site Type

- Cabin**
 Allotment
 Camp
 RAWS
 Historical
 Homestead
 Construction
 Archeological
 Communications
 Mining
 Camp
 Trade&Mfg
 Allotment
 T&ESpecies
 Mech.Equip.
 Headquarters
 Other

Quad Name _____ Lat 64° 19.667 TWN/RNG/SEC _____
 Quad _____ Long -146° 56.430 Allotment #35 _____
 Number _____
 Owner Bill Hamsley Phone 907-669-2680 Permit # _____
 Address 5 Mile Clear Creek

Description of Location

Third structure on 5 Mile Clear Creek on river left (looking down river).

2 total structures on site, cabin, out house. Wooden construction with metal roof and screened-in porch.

Fire Management Option (Site Protection Level)

- Limited**
 Modified
 Avoid
 Pending determination
 Full
 Critical
 Non-sensitive

Land Status

- BLM
 NPS
 State
 Trespass
 FWS
 USFS
 Military
 Private
 Native Corporation

Cabin Description

- | | | | | |
|---|--|---|---|--|
| Cabin Construction
<input type="checkbox"/> Log
<input checked="" type="checkbox"/> Frame
<input type="checkbox"/> Other
<u>1 # of outbuildings</u> | Foundation
<input type="checkbox"/> Closed
<input checked="" type="checkbox"/> Open
<input checked="" type="checkbox"/> Deck
<input type="checkbox"/> Other | Roof Type
<input checked="" type="checkbox"/> Metal
<input type="checkbox"/> Shake
<input type="checkbox"/> Composite
<input type="checkbox"/> Sod
<input type="checkbox"/> Tarp | Condition of Cabin
<input type="checkbox"/> Complete structure
<input type="checkbox"/> Walls without roof
<input type="checkbox"/> Under construction
<input type="checkbox"/> Walls & roof collapsed
<input type="checkbox"/> Cabin site, remains | Hazardous Materials
<input type="checkbox"/> None
<input type="checkbox"/> Empty fuel cans
<input checked="" type="checkbox"/> Full fuel cans
<input type="checkbox"/> Batteries
<input type="checkbox"/> Other |
|---|--|---|---|--|

Description (outbuildings, docks, machinery, defensible space, etc.)

2 Total structures and wooden dock on site accessible by boat. Black Spruce has been thinned by 1 chain around the main structure.

One sprinkler kit has been set up, ran by 1 Shindaiwa.

Vegetation/Fuel Inventory

- | | | | | |
|---|--|--|--|--|
| Over-story
<input type="checkbox"/> White Spruce
<input checked="" type="checkbox"/> Black Spruce
<input type="checkbox"/> Mixed
_____ % Hardwoods
_____ % Conifer | Average Tree Height
_____ Spruce <u>30ft</u>
_____ Hardwood | Understory
<input type="checkbox"/> Tall Shrub >6 ft
<input type="checkbox"/> Short Shrub <6 ft
<input checked="" type="checkbox"/> Grass/Forbes
<input checked="" type="checkbox"/> Moss/Lichens | Canopy Closure
<input checked="" type="checkbox"/> Closed >50%
<input type="checkbox"/> Open 10-49% | Ladder Fuels
<input checked="" type="checkbox"/> Yes
<input type="checkbox"/> No |
|---|--|--|--|--|

Fuels Description

Terrain

- Slope**
 0-25%
 51-75%
 26-50%
 76-100%
- Aspect**
 N
 E
 S
 W
 NE
 SE
 SW
 NW
 Flat

Suppression Data

- Water Source**
 Location/Description 5 Mile Clear Creek
- Helispot**
 Location/Description 64 19.578', 146 55.838'
- Other Access**
 Location/Description Jet, or airboat access only from Salcha boat launch. Sacha River to Tanana to 5 MI Clear Creek.

Notes:

- Inhabited
 Photo included
 Sketch of plumbing set up on back



CC4 Site Assessment Survey

Date 7/7/15 Time 12:00

Site Assessor UnawEEP WFM

Site Type

- Cabin**
 Allotment
 Camp
 RAWS
 Historical
 Homestead
 Construction
 Archeological
 Communications
 Mining
 Camp
 Trade&Mfg
 Allotment
 T&ESpecies
 Mech.Equip.
 Headquarters
 Other

Quad Name _____ Lat _____ TWN/RNG/SEC _____
 Quad _____ Long _____ Allotment #34 _____
 Number _____
 Owner Mike Woods Phone 907-388-9874 Permit # _____
 Address 5 Mile Clear Creek

Description of Location

Fourth structure on 5 Mile Clear Creek on river right (looking down river).
 3 total structures on site, main cabin, storage shed, outhouse.
 Wood construction with blue trim

Fire Management Option (Site Protection Level)

- Limited
 Modified
 Avoid
 Pending determination

- Full
 Critical
 Non-sensitive

Land Status

- BLM
 NPS
 State
 Trespass
 FWS
 USFS
 Military
 Private
 Native Corporation _____

Cabin Description

Cabin Construction

- Log
 Frame
 Other
2 # of outbuildings

Foundation

- Closed
 Open
 Deck
 Other

Roof Type

- Metal
 Shake
 Composite
 Sod
 Blue tarp

Condition of Cabin

- Complete structure
 Walls without roof
 Under construction
 Walls & roof collapsed
 Cabin site, remains

Hazardous Materials

- None
 Empty fuel cans
 Full fuel cans
 Batteries
 Other

Description (outbuildings, docks, machinery, defensible space, etc.)

3 Total structures on site accessible by boat. Open deck facing the creek. Black Spruce has been thinned by 1 chain around the main structure. Two sprinkler kits have been set up, ran by 1 mark 3.

Vegetation/Fuel Inventory

Over-story

- White Spruce
 Black Spruce
 Mixed
 _____ % Hardwoods
 _____ % Conifer

Average Tree Height

_____ Spruce 30ft
 _____ Hardwood

Understory

- Tall Shrub >6 ft
 Short Shrub <6 ft
 Grass/Forbes
 Moss/Lichens

Canopy Closure

- Closed >50%
 Open 10-49%

Ladder Fuels

- Yes
 No

Fuels Description

Terrain

Slope

- 0-25%
 51-75%
 26-50%
 76-100%

Aspect

- N
 E
 S
 W
 NE
 SE
 SW
 NW
 Flat

Suppression Data

Water Source

Location/Description 5 Mile Clear Creek

Helispot

Location/Description 64 19.578', 146 55.838'

Other Access

Location/Description Jet, or airboat access only from Salcha boat launch. Sacha River to Tanana to 5 MI Clear Creek.

Notes:

- Inhabited
 Photo included
 Sketch of plumbing set up on back



CC5 Site Assessment Survey

Date 7/7/15 Time 12:00

Site Assessor Unawep WFM

Site Type

- Cabin**
 Allotment
 Camp
 RAWS
 Historical
 Homestead
 Construction
 Archeological
 Communications
 Mining
 Camp
 Trade&Mfg
 Allotment
 T&ESpecies
 Mech.Equip.
 Headquarters
 Other

Quad Name _____ Lat 64° 19.532 TWN/RNG/SEC _____
 Quad _____ Long -146° 55.923 Allotment #14 _____
 Number _____
 Owner Fred Kuykendall Phone 907-590-4622 Permit # _____
 Address 5 Mile Clear Creek

Description of Location

Fifth structure on 5 Mile Clear Creek on river right (looking down river).

6 total structures on site: cabin, out house, fuel shed, generator shed, hot tub and greenhouse. Wooden construction with metal roof.

Fire Management Option (Site Protection Level)

- Limited**
 Modified
 Avoid
 Pending determination
 Full
 Critical
 Non-sensitive

Land Status

- BLM
 NPS
 State
 Trespass
 FWS
 USFS
 Military
 Private
 Native Corporation _____

Cabin Description

Cabin Construction

- Log**
 Frame
 Other
6 # of outbuildings

Foundation

- Closed
 Open
 Deck
 Other

Roof Type

- Metal**
 Shake
 Composite
 Sod
 Tarp

Condition of Cabin

- Complete structure**
 Walls without roof
 Under construction
 Walls & roof collapsed
 Cabin site, remains

Hazardous Materials

- None
 Empty fuel cans
 Full fuel cans
 Batteries
 Other

Description (outbuildings, docks, machinery, defensible space, etc.)

6 Total structures on site accessible by boat. Several outbuildings tucked into thicker stands of mixed black and white spruce. Black

Spruce has been thinned by 1 chain around the main structure. Two sprinkler kits have been set up; ran by 1 Mark 3 pump.

Vegetation/Fuel Inventory

Over-story

- White Spruce**
 Black Spruce
 Mixed
 _____ % Hardwoods
100% Conifer

Average Tree Height

_____ Spruce **50ft**
 _____ Hardwood

Understory

- Tall Shrub >6 ft
 Short Shrub <6 ft
 Grass/Forbes
 Moss/Lichens

Canopy Closure

- Closed >50%**
 Open 10-49%

Ladder Fuels

- Yes**
 No

Fuels Description

Black Spruce around the outer periphery of main structure, but fuels immediately around main structure is mature white spruce without ladder fuels and some spacing in the canopy.

Terrain

Slope

- 0-25%**
 51-75%
 26-50%
 76-100%

Aspect

- N
 E
 S
 W
 NE
 SE
 SW
 NW
 Flat

Suppression Data

Water Source

Location/Description 5 Mile Clear Creek

Helispot

Location/Description 64 19.578', 146 55.838'

Other Access


Location/Description Jet, or airboat access only from Salcha boat launch. Sacha River to Tanana to 5 MI Clear Creek.

Notes:

Inhabited

Photo included

Sketch of plumbing set up on back



CC6 Site Assessment Survey

Date 7/7/15 Time 12:00

Site Assessor Unawep WFM

Site Type

- Cabin**
 Allotment
 Camp
 RAWS
 Historical
 Homestead
 Construction
 Archeological
 Communications
 Mining
 Camp
 Trade&Mfg
 Allotment
 T&ESpecies
 Mech.Equip.
 Headquarters
 Other

Quad Name _____ Lat 64° 19.403 TWN/RNG/SEC _____
 Quad _____ Long -146° 55.903 Allotment #13 _____
 Number _____
 Owner Miles Walker Phone Unknown Permit # _____
 Address 5 Mile Clear Creek

Description of Location

Sixth structure on 5 Mile Clear Creek on river left (looking down river).

3 total structures on site: cabin, out house and shed. Wooden construction with metal roof.

Fire Management Option (Site Protection Level)

- Limited**
 Modified
 Avoid
 Pending determination

- Full
 Critical
 Non-sensitive

Land Status

- BLM
 NPS
 State
 Trespass
 FWS
 USFS
 Military
 Private
 Native Corporation

Cabin Description

Cabin Construction

- Log
 Frame
 Other
3 # of outbuildings

Foundation

- Closed
 Open
 Deck
 Other

Roof Type

- Metal**
 Shake
 Composite
 Sod
 Tarp

Condition of Cabin

- Complete structure**
 Walls without roof
 Under construction
 Walls & roof collapsed
 Cabin site, remains

Hazardous Materials

- None
 Empty fuel cans
 Full fuel cans
 Batteries
 Other

Description (outbuildings, docks, machinery, defensible space, etc.)

3 total structures on site, accessible by boat. Black Spruce has been thinned by 1 chain around the main structure. One sprinkler kit has been set up; ran by 1 Shindaiwa pump.

Vegetation/Fuel Inventory

Over-story

- White Spruce**
 Black Spruce
 Mixed
 _____ % Hardwoods
100% Conifer

Average Tree Height

_____ Spruce **50ft**
 _____ Hardwood

Understory

- Tall Shrub >6 ft
 Short Shrub <6 ft
 Grass/Forbes
 Moss/Lichens

Canopy Closure

- Closed >50%**
 Open 10-49%

Ladder Fuels

- Yes**
 No

Fuels Description

Black Spruce around the periphery of main structure, but fuels immediately around main structure is mature white spruce without ladder fuels and some open spacing in the canopy.

Terrain

Slope

- 0-25%**
 51-75%
 26-50%
 76-100%

Aspect

- N
 E
 S
 W
 NE
 SE
 SW
 NW
 Flat

Suppression Data

Water Source

Location/Description 5 Mile Clear Creek

Helispot

Location/Description 64 19.578', 146 55.838'

Other Access

Location/Description Jet, or airboat access only from Salcha boat launch. Sacha River to Tanana to 5 MI Clear Creek.

Notes:

- Inhabited
 Photo included
 Sketch of plumbing set up on back



CC 7 Site Assessment Survey

Date 7/7/15 Time 12:00

Site Assessor Unawep WFM

Site Type

- Cabin**
 Allotment
 Camp
 RAWS
 Historical
 Homestead
 Construction
 Archeological
 Communications
 Mining
 Camp
 Trade&Mfg
 Allotment
 T&ESpecies
 Mech.Equip.
 Headquarters
 Other

Quad Name _____ Lat 64° 19.328 TWN/RNG/SEC _____
 Quad _____ Long -146° 55.763 Allotment #30 _____
 Number _____
 Owner Steve Lambert Phone 907-444-0967 Permit # _____
 Address 5 Mile Clear Creek

Description of Location

Seventh structure on 5 Mile Clear Creek on river left (looking down river).

1 total structures on site: cabin. Wooden construction.

Fire Management Option (Site Protection Level)

- Limited**
 Modified
 Avoid
 Pending determination
 Full
 Critical
 Non-sensitive

Land Status

- BLM
 NPS
 State
 FWS
 USFS
 Military
 Private
 Native Corporation

Cabin Description

Cabin Construction

- Log
 Frame
 Other
1 # of outbuildings 0

Foundation

- Closed
 Open
 Deck
 Other

Roof Type

- Metal
 Shake
 Composite
 Sod
 Tarp
 Other

Condition of Cabin

- Complete structure
 Walls without roof
 Under construction
 Walls & roof collapsed
 Cabin site, remains

Hazardous Materials

- None
 Empty fuel cans
 Full fuel cans
 Batteries
 Other

Description (outbuildings, docks, machinery, defensible space, etc.)

1 total structures on site, accessible by boat. Structure is a finished platform for a wall tent with spaced planks on top and

miscellaneous items stored beneath. Black Spruce has been thinned by 1 chain around the main structure. One sprinkler kit has been set up; ran by 1 Shindaiwa pump.

Vegetation/Fuel Inventory

Over-story

- White Spruce**
 Black Spruce
 Mixed
 _____ % Hardwoods
100% Conifer

Average Tree Height

_____ Spruce 50ft
 _____ Hardwood

Understory

- Tall Shrub >6 ft
 Short Shrub <6 ft
 Grass/Forbes
 Moss/Lichens

Canopy Closure

- Closed >50%**
 Open 10-49%

Ladder Fuels

- Yes**
 No

Fuels Description

Fuels immediately around main structure is mature white spruce without ladder fuels and some open spacing in the canopy. Mostly white spruce around outer periphery with some hardwoods mixed in.

Terrain

Slope

- 0-25%**
 51-75%
 26-50%
 76-100%

Aspect

- N
 E
 S
 W
 NE
 SE
 SW
 NW
 Flat

Suppression Data

Water Source

Location/Description 5 Mile Clear Creek

Helispot

Location/Description 64 19.578', 146 55.838'

Other Access

Location/Description Jet, or airboat access only from Salcha boat launch. Sacha River to Tanana to 5 MI Clear Creek.

Notes:

Inhabited

Photo included

Sketch of plumbing set up on back



CC8 Site Assessment Survey

Date 7/7/15 Time 12:00

Site Assessor Unawep WFM

Site Type

- Cabin**
 Allotment
 Camp
 RAWS
 Historical
 Homestead
 Construction
 Archeological
 Communications
 Mining
 Camp
 Trade&Mfg
 Allotment
 T&ESpecies
 Mech.Equip.
 Headquarters
 Other

Quad Name _____ Lat 64° 19.345 TWN/RNG/SEC _____
 Quad _____ Long -146° 55.718 Allotment #33 _____
 Number _____
 Owner Steve Vincent Phone 907-378-1899 Permit # _____
 Address 5 Mile Clear Creek

Description of Location

Eighth structure on 5 Mile Clear Creek on river right (looking down river).

3 total structures on site: cabin, out house and shed. Wooden construction with metal roof.

Fire Management Option (Site Protection Level)

- Limited**
 Modified
 Avoid
 Pending determination
 Full
 Critical
 Non-sensitive

Land Status

- BLM
 NPS
 State
 Trespass
 FWS
 USFS
 Military
 Private
 Native Corporation

Cabin Description

Cabin Construction

- Log
 Frame
 Other
3 # of outbuildings

Foundation

- Closed
 Open
 Deck
 Other

Roof Type

- Metal**
 Shake
 Composite
 Sod
 Tarp

Condition of Cabin

- Complete structure**
 Walls without roof
 Under construction
 Walls & roof collapsed
 Cabin site, remains

Hazardous Materials

- None
 Empty fuel cans
 Full fuel cans
 Batteries
 Other

Description (outbuildings, docks, machinery, defensible space, etc.)

3 total structures on site, accessible by boat. Structure is a finished cabin with two outbuildings. She'd is located in slightly thicker stand of spruce. Black Spruce has been thinned by 1 chain around the main structure. Two sprinkler kits have been set up; ran by 1 Mark 3 pump.

Vegetation/Fuel Inventory

Over-story

- White Spruce**
 Black Spruce
 Mixed
 _____ % Hardwoods
100% Conifer

Average Tree Height

_____ **Spruce 30-50ft**
 _____ Hardwood

Understory

- Tall Shrub >6 ft
 Short Shrub <6 ft
 Grass/Forbes
 Moss/Lichens

Canopy Closure

- Closed >50%**
 Open 10-49%

Ladder Fuels

- Yes**
 No

Fuels Description

Fuels immediately around main structure is mostly mature white spruce without ladder fuels and some open spacing in the canopy. Outer periphery has larger black spruce component and denser stands further out.

Terrain

Slope

- 0-25%**
 51-75%
 26-50%
 76-100%

Aspect

- N
 E
 S
 W
 NE
 SE
 SW
 NW
 Flat

Suppression Data

Water Source

Location/Description 5 Mile Clear Creek

Helispot

Location/Description 64 19.578', 146 55.838'

Other Access

Location/Description Jet, or airboat access only from Salcha boat launch. Sacha River to Tanana to 5 MI Clear Creek.

Notes:

Inhabited

Photo included

Sketch of plumbing set up on back



CC9 Site Assessment Survey

Date 7/7/15 Time 12:00

Site Assessor Unaweeep WFM

Site Type

- Cabin**
 Allotment
 Camp
 RAWS
 Historical
 Homestead
 Construction
 Archeological
 Communications
 Mining
 Camp
 Trade&Mfg
 Allotment
 T&ESpecies
 Mech.Equip.
 Headquarters
 Other

Quad Name _____ Lat 64° 19.332 TWN/RNG/SEC _____
 Quad _____ Long -146° 55.227 Allotment #32 _____
 Number _____
 Owner Mike Stark Phone 907-378-9618 Permit # _____
 Address 5 Mile Clear Creek

Description of Location

Ninth structure on 5 Mile Clear Creek on river right (looking down river).
 4 total structures on site: cabin, out house, shed and hot tub. Wooden construction with metal roof.

Fire Management Option (Site Protection Level)

- Limited**
 Modified
 Avoid
 Pending determination
 Full
 Critical
 Non-sensitive

Land Status

- BLM
 NPS
 State
 Trespass
 FWS
 USFS
 Military
 Private
 Native Corporation

Cabin Description

- | | | | | |
|---|--|---|---|--|
| Cabin Construction
<input type="checkbox"/> Log
<input checked="" type="checkbox"/> Frame
<input type="checkbox"/> Other
<u>4 # of outbuildings</u> | Foundation
<input type="checkbox"/> Closed
<input checked="" type="checkbox"/> Open
<input checked="" type="checkbox"/> Deck
<input type="checkbox"/> Other | Roof Type
<input checked="" type="checkbox"/> Metal
<input type="checkbox"/> Shake
<input type="checkbox"/> Composite
<input type="checkbox"/> Sod
<input type="checkbox"/> Tarp | Condition of Cabin
<input checked="" type="checkbox"/> Complete structure
<input type="checkbox"/> Walls without roof
<input type="checkbox"/> Under construction
<input type="checkbox"/> Walls & roof collapsed
<input type="checkbox"/> Cabin site, remains | Hazardous Materials
<input type="checkbox"/> None
<input type="checkbox"/> Empty fuel cans
<input checked="" type="checkbox"/> Full fuel cans
<input type="checkbox"/> Batteries
<input type="checkbox"/> Other |
|---|--|---|---|--|

Description (outbuildings, docks, machinery, defensible space, etc.)

4 total structures on site, accessible by boat. Structure is a finished cabin with two outbuildings, a large hot tub with deck, and a wooden dock. Black Spruce has been thinned by 1 chain around the main structure. Two sprinkler kits have been set up; ran by 1 Wick 375 pump.

Vegetation/Fuel Inventory

- | | | | | |
|---|---|--|--|--|
| Over-story
<input checked="" type="checkbox"/> White Spruce
<input checked="" type="checkbox"/> Black Spruce
<input type="checkbox"/> Mixed
_____ % Hardwoods
100% Conifer | Average Tree Height
_____ Spruce 30-50ft
_____ Hardwood | Understory
<input type="checkbox"/> Tall Shrub >6 ft
<input type="checkbox"/> Short Shrub <6 ft
<input checked="" type="checkbox"/> Grass/Forbes
<input checked="" type="checkbox"/> Moss/Lichens | Canopy Closure
<input checked="" type="checkbox"/> Closed >50%
<input type="checkbox"/> Open 10-49% | Ladder Fuels
<input checked="" type="checkbox"/> Yes
<input type="checkbox"/> No |
|---|---|--|--|--|

Fuels Description

Fuel Immediately around main structure is white and black spruce mix with thick ladder fuels on the down river side and some open spacing in the canopy on the up river side. Outer periphery has larger black spruce component and denser stands further out.

Terrain

- Slope**
 0-25%
 51-75%
 26-50%
 76-100%
- Aspect**
 N
 E
 S
 W
 NE
 SE
 SW
 NW
 Flat

Suppression Data

- Water Source**
 Location/Description 5 Mile Clear Creek
- Helispot**
 Location/Description 64 19.578', 146 55.838'
- Other Access**
 Location/Description Jet, or airboat access only from Salcha boat launch. Sacha River to Tanana to 5 MI Clear Creek.

Notes:

- Inhabited
 Photo included
 Sketch of plumbing set up on back



CC10 Site Assessment Survey

Date 7/7/15 Time 12:00

Site Assessor Unawep WFM

Site Type

- Cabin Allotment Camp RAWS Historical Homestead Construction Archeological Communications Mining Camp Trade&Mfg Allotment T&ESpecies Mech.Equip. Headquarters Other

Quad Name Lat 64° 19.025 TWN/RNG/SEC
Quad Long -146° 54.475 Allotment #11
Owner Brad & Brian Dietrich Phone 907-987-6984 - 907-388-1765 -
Address 5 Mile Clear Creek

Description of Location

Tenth structure on 5 Mile Clear Creek on river right (looking down river).
3 total structures on site: cabin, out house, and shed. Wooden construction with metal roof.

Fire Management Option (Site Protection Level)

- Limited Modified Avoid Pending determination

- Full Critical Non-sensitive

Land Status

- BLM FWS Native Corporation NPS USFS State Military Private Trespass

Cabin Description

Cabin Construction

- Log Frame Other # of outbuildings 2

Foundation

- Closed Open Deck Other

Roof Type

- Metal Shake Composite Sod Tarp

Condition of Cabin

- Complete structure Walls without roof Under construction Walls & roof collapsed Cabin site, remains

Hazardous Materials

- None Empty fuel cans Full fuel cans Batteries Other

Description (outbuildings, docks, machinery, defensible space, etc.)

3 total structures on site, accessible by boat. Structure is a finished cabin with two outbuildings. Black Spruce has been thinned by 1 chain around the main structure. Two sprinkler kits have been set up; ran by 1 Mark 3 pump.

Vegetation/Fuel Inventory

Over-story

- White Spruce Black Spruce Mixed % Hardwoods 100% Conifer

Average Tree Height

Spruce 30-50ft Hardwood

Understory

- Tall Shrub >6 ft Short Shrub <6 ft Grass/Forbes Moss/Lichens

Canopy Closure

- Closed >50% Open 10-49%

Ladder Fuels

- Yes No

Fuels Description

Terrain

Slope

- 0-25% 51-75% 26-50% 76-100%

Aspect

- N E S W NE SE SW NW Flat

Suppression Data

Water Source

Location/Description 5 Mile Clear Creek

Helispot

Location/Description 64 19.578', 146 55.838'

Other Access

Location/Description Jet, or airboat access only from Salcha boat launch. Sacha River to Tanana to 5 MI Clear Creek.

Notes:

- Inhabited Photo included Sketch of plumbing set up on back



CC11 Site Assessment Survey

Date 7/7/15 Time 12:00

Site Assessor Unawweep WFM

Site Type

- Cabin**
 Allotment
 Camp
 RAWS
 Historical
 Homestead
 Construction
 Archeological
 Communications
 Mining
 Camp
 Trade&Mfg
 Allotment
 T&ESpecies
 Mech.Equip.
 Headquarters
 Other

Quad Name _____ Lat 64° 18.927 TWN/RNG/SEC _____
 Quad _____ Long -146° 54.230 Allotment #9 _____
 Number _____
 Owner Herbert Mann Phone 907-457-6020 Permit # _____
 Address 5 Mile Clear Creek

Description of Location

Eleventh structure on 5 Mile Clear Creek on river left (looking down river).
 2 total structures on site: cabin and out house. Metal siding with metal roof.

Fire Management Option (Site Protection Level)

- Limited**
 Modified
 Avoid
 Pending determination
 Full
 Critical
 Non-sensitive

Land Status

- BLM
 NPS
 State
 Trespass
 FWS
 USFS
 Military
 Private
 Native Corporation

Cabin Description

- | | | | | |
|--|--|--|---|--|
| Cabin Construction
<input type="checkbox"/> Log
<input checked="" type="checkbox"/> Frame
<input type="checkbox"/> Other
2 # of outbuildings _____ | Foundation
<input type="checkbox"/> Closed
<input checked="" type="checkbox"/> Open
<input type="checkbox"/> Deck
<input type="checkbox"/> Other | Roof Type
<input checked="" type="checkbox"/> Metal
<input type="checkbox"/> Shake
<input type="checkbox"/> Composite
<input type="checkbox"/> Sod
<input checked="" type="checkbox"/> Tarp | Condition of Cabin
<input checked="" type="checkbox"/> Complete structure
<input type="checkbox"/> Walls without roof
<input type="checkbox"/> Under construction
<input type="checkbox"/> Walls & roof collapsed
<input type="checkbox"/> Cabin site, remains | Hazardous Materials
<input type="checkbox"/> None
<input checked="" type="checkbox"/> Empty fuel cans
<input type="checkbox"/> Full fuel cans
<input type="checkbox"/> Batteries
<input type="checkbox"/> Other |
|--|--|--|---|--|

Description (outbuildings, docks, machinery, defensible space, etc.)

2 total structures on site, accessible by boat. Structure is a finished cabin with one outbuilding. Black Spruce has been thinned by 1 chain around the main structure. One sprinkler kit has been set up; ran by 1 Shindaiwa pump.

Vegetation/Fuel Inventory

- | | | | | |
|---|---|--|--|--|
| Over-story
<input checked="" type="checkbox"/> White Spruce
<input checked="" type="checkbox"/> Black Spruce
<input type="checkbox"/> Mixed
_____ % Hardwoods
100% Conifer | Average Tree Height
_____ Spruce 30-50ft
_____ Hardwood | Understory
<input type="checkbox"/> Tall Shrub >6 ft
<input type="checkbox"/> Short Shrub <6 ft
<input checked="" type="checkbox"/> Grass/Forbes
<input checked="" type="checkbox"/> Moss/Lichens | Canopy Closure
<input checked="" type="checkbox"/> Closed >50%
<input type="checkbox"/> Open 10-49% | Ladder Fuels
<input checked="" type="checkbox"/> Yes
<input type="checkbox"/> No |
|---|---|--|--|--|

Fuels Description

Terrain

- Slope**
 0-25%
 51-75%
 26-50%
 76-100%
Aspect
 N
 E
 S
 W
 NE
 SE
 SW
 NW
 Flat

Suppression Data

- Water Source**
 Location/Description 5 Mile Clear Creek
 Helispot
 Location/Description 64 19.578', 146 55.838'
 Other Access
 Location/Description Jet, or airboat access only from Salcha boat launch. Sacha River to Tanana to 5 MI Clear Creek.

Notes:

- Uninhabited
 Photo included
 Sketch of plumbing set up on back



CC12 Site Assessment Survey

Date 7/7/15 Time 12:00

Site Assessor UnawEEP WFM

Site Type

- Cabin**
 Allotment
 Camp
 RAWS
 Historical
 Homestead
 Construction
 Archeological
 Communications
 Mining
 Camp
 Trade&Mfg
 Allotment
 T&ESpecies
 Mech.Equip.
 Headquarters
 Other

Quad Name _____ Lat 64° 18.917 TWN/RNG/SEC _____
 Quad _____ Long -146° 54.142 Allotment #9 _____
 Number _____
 Owner Don Kholer Phone 907-378-5338 Permit # _____
 Address 5 Mile Clear Creek

Description of Location

Twelfth structure on 5 Mile Clear Creek on river right (looking down river).

2 total structures on site: cabin and out house. Wooden construction with metal roof.

Fire Management Option (Site Protection Level)

- Limited**
 Modified
 Avoid
 Pending determination
 Full
 Critical
 Non-sensitive

Land Status

- BLM
 NPS
 State
 Trespass
 FWS
 USFS
 Military
 Private
 Native Corporation _____

Cabin Description

Cabin Construction

- Log
 Frame
 Other
2# of outbuildings 1

Foundation

- Closed
 Open
 Deck
 Other

Roof Type

- Metal**
 Shake
 Composite
 Sod
 Tarp

Condition of Cabin

- Complete structure**
 Walls without roof
 Under construction
 Walls & roof collapsed
 Cabin site. remains

Hazardous Materials

- None
 Empty fuel cans
 Full fuel cans
 Batteries
 Other

Description (outbuildings, docks, machinery, defensible space, etc.)

2 total structures on site, accessible by boat. Structure is a finished cabin with one outbuilding. Black Spruce has been thinned by 1 chain around the main structure. One sprinkler kit has been set up; ran by 1 Shindaiwa pump.

Over-story

- White Spruce**
 Black Spruce
 Mixed
 % Hardwoods _____
100% Conifer

Average Tree Height

Spruce 30-50ft
 _____ Hardwood

Vegetation/Fuel Inventory

Understory

- Tall Shrub >6 ft
 Short Shrub <6 ft
 Grass/Forbes
 Moss/Lichens

Canopy Closure

- Closed >50%**
 Open 10-49%

Ladder Fuels

- Yes**
 No

Fuels Description

Terrain

Slope

- 0-25%**
 51-75%
 26-50%
 76-100%

Aspect

- N
 E
 S
 W
 NE
 SE
 SW
 NW
 Flat

Suppression Data

Water Source

Location/Description 5 Mile Clear Creek

Helispot

Location/Description 64 19.578', 146 55.838'

Other Access

Location/Description Jet, or airboat access only from Salcha boat launch. Sacha River to Tanana to 5 MI Clear Creek.

Notes:

- Inhabited
 Photo included
 Sketch of plumbing set up on back



CC13 Site Assessment Survey

Date 7/7/15 Time 12:00

Site Assessor UnawEEP WFM

Site Type

- Cabin** Allotment Camp RAWS Historical Homestead Construction Archeological Communications
 Mining Camp Trade&Mfg Allotment T&ESpecies Mech.Equip. Headquarters Other _____

Quad Name _____ Lat 64° 18.888 TWN/RNG/SEC _____
 Quad _____ Long -146° 54.083 Allotment #7 _____
 Number _____
 Owner Shelly Curtis Phone 907-388-5649 Permit # _____
 Address 5 Mile Clear Creek

Description of Location

Thirteenth structure on 5 Mile Clear Creek on river left (looking down river).
 3 total structures on site: cabin, shed and out house. Wooden construction with metal roof.

Fire Management Option (Site Protection Level)

- Limited** Full
 Modified Critical
 Avoid Non-sensitive
 Pending determination

Land Status

- BLM NPS State Trespass
 FWS USFS Military **Private**
 Native Corporation _____

Cabin Description

- | | | | | |
|--|--|---|---|--|
| Cabin Construction
<input type="checkbox"/> Log
<input checked="" type="checkbox"/> Frame
<input type="checkbox"/> Other
<u>3</u> # of outbuildings. | Foundation
<input type="checkbox"/> Closed
<input checked="" type="checkbox"/> Open
<input checked="" type="checkbox"/> Deck
<input type="checkbox"/> Other | Roof Type
<input checked="" type="checkbox"/> Metal
<input type="checkbox"/> Shake
<input type="checkbox"/> Composite
<input type="checkbox"/> Sod
<input type="checkbox"/> Tarp | Condition of Cabin
<input checked="" type="checkbox"/> Complete structure
<input type="checkbox"/> Walls without roof
<input type="checkbox"/> Under construction
<input type="checkbox"/> Walls & roof collapsed
<input type="checkbox"/> Cabin site, remains | Hazardous Materials
<input type="checkbox"/> None
<input type="checkbox"/> Empty fuel cans
<input checked="" type="checkbox"/> Full fuel cans
<input type="checkbox"/> Batteries
<input type="checkbox"/> Other |
|--|--|---|---|--|

Description (outbuildings, docks, machinery, defensible space, etc.)

3 total structures on site, accessible by boat. Structure is a finished cabin with two outbuildings and a wooden dock. Black Spruce has been thinned by 1 chain around the main structure. Two sprinkler kits have been set up; ran by one Wick 375 pump.

Vegetation/Fuel Inventory

- | | | | | |
|---|---|--|--|--|
| Over-story
<input checked="" type="checkbox"/> White Spruce
<input checked="" type="checkbox"/> Black Spruce
<input type="checkbox"/> Mixed
_____ % Hardwoods
100% Conifer | Average Tree Height
_____ Spruce 30 ft
_____ Hardwood | Understory
<input type="checkbox"/> Tall Shrub >6 ft
<input type="checkbox"/> Short Shrub <6 ft
<input checked="" type="checkbox"/> Grass/Forbes
<input checked="" type="checkbox"/> Moss/Lichens | Canopy Closure
<input checked="" type="checkbox"/> Closed >50%
<input type="checkbox"/> Open 10-49% | Ladder Fuels
<input checked="" type="checkbox"/> Yes
<input type="checkbox"/> No |
|---|---|--|--|--|

Fuels Description

Terrain

- Slope**
 0-25% 51-75% 26-50% 76-100%
- Aspect**
 N E S W NE SE SW NW **Flat**

Suppression Data

- Water Source**
 Location/Description 5 Mile Clear Creek
- Helispot**
 Location/Description 64 19.578', 146 55.838'
- Other Access**
 Location/Description Jet, or airboat access only from Salcha boat launch. Sacha River to Tanana to 5 MI Clear Creek.

Notes:

- Inhabited** **Photo included** **Sketch of plumbing set up on back**



CC14 Site Assessment Survey

Date 7/7/15 Time 12:00

Site Assessor Unawep WFM

Site Type

- Site type checkboxes: Cabin, Allotment, Camp, RAWS, Historical, Homestead, Construction, Archeological, Communications, Mining, Trade&Mfg, T&ESpecies, Mech.Equip, Headquarters, Other

Quad Name, Lat, Long, TWN/RNG/SEC, Allotment #27, Owner: Bob Groseclose, Phone: 907-457-5498, 907-425-1855, Address: 5 Mile Clear Creek

Description of Location

Fourteenth structure on 5 Mile Clear Creek on river right (looking down river). 3 total structures on site: cabin, shed and out house. Wooden construction with metal roof.

Fire Management Option (Site Protection Level)

- Fire Management checkboxes: Limited, Modified, Avoid, Pending determination, Full, Critical, Non-sensitive

Land Status

- Land Status checkboxes: BLM, FWS, Native Corporation, NPS, USFS, State, Military, Trespass, Private

Cabin Description

- Cabin Description checkboxes: Construction (Log, Frame, Other), Foundation (Closed, Open, Deck, Other), Roof Type (Metal, Shake, Composite, Sod, Tarp), Condition of Cabin (Complete structure, Walls without roof, Under construction, Walls & roof collapsed), Hazardous Materials (None, Empty fuel cans, Full fuel cans, Batteries)

Description (outbuildings, docks, machinery, defensible space, etc.)

1 structure on site, accessible by boat. Structure is a finished cabin. Black Spruce has been thinned by 1 chain around the main structure. Two sprinkler kits have been set up; ran by one Wick 375 pump.

Vegetation/Fuel Inventory

- Vegetation/Fuel Inventory checkboxes: Over-story (White Spruce, Black Spruce, Mixed, % Hardwoods, % Conifer), Average Tree Height (Spruce 30 ft, Hardwood), Understory (Tall Shrub >6 ft, Short Shrub <6 ft, Grass/Forbes, Moss/Lichens), Canopy Closure (Closed >50%, Open 10-49%), Ladder Fuels (Yes, No)

Fuels Description

Terrain

- Terrain checkboxes: Slope (0-25%, 51-75%, 26-50%, 76-100%), Aspect (N, E, S, W, NE, SE, SW, NW, Flat)

Suppression Data

- Suppression Data checkboxes: Water Source (Location/Description: 5 Mile Clear Creek), Helispot (Location/Description: 64 19.578', 146 55.838'), Other Access (Location/Description: Jet, or airboat access only from Salcha boat launch. Sacha River to Tanana to 5 MI Clear Creek.)

Notes:

- Notes checkboxes: Inhabited, Photo included, Sketch of plumbing set up on back



CC15 Site Assessment Survey

Date 7/7/15 Time 12:00

Site Assessor UnawEEP WFM

Site Type

- Cabin**
 Allotment
 Camp
 RAWS
 Historical
 Homestead
 Construction
 Archeological
 Communications
 Mining
 Camp
 Trade&Mfg
 Allotment
 T&ESpecies
 Mech.Equip.
 Headquarters
 Other

Quad Name _____ Lat 64° 18.604 TWN/RNG/SEC _____
 Quad _____ Long -146° 53.203 Allotment #5 _____
 Number _____
 Owner Adam Knopp Phone 907-687-7395 Permit# _____
 Address 5 Mile Clear Creek

Description of Location

Fifteenth structure on 5 Mile Clear Creek on river right (looking down river).

2 total structures on site: log cabin (currently under active construction) and wall tent. Wooden construction with metal roof.

Fire Management Option (Site Protection Level)

- Limited**
 Modified
 Avoid
 Pending determination

- Full
 Critical
 Non-sensitive

Land Status

- BLM
 NPS
 State
 Trespass
 FWS
 USFS
 Military
 Private
 Native Corporation _____

Cabin Description

Cabin Construction

- Log**
 Frame
 Other
2 # of outbuildings 0

Foundation

- Closed
 Open
 Deck
 Other

Roof Type

- Metal
 Shake
 Composite
 Sod
 Tarp

Condition of Cabin

- Complete structure
 Walls without roof
 Under construction
 Walls & roof collapsed
 Cabin site, remains

Hazardous Materials

- None
 Empty fuel cans
 Full fuel cans
 Batteries
 Other

Description (outbuildings, docks, machinery, defensible space, etc.)

2 structures on site, accessible by boat. Structure is a unfinished cabin with one wall tent. Cabin is currently, and actively, under construction. Black Spruce has been thinned by 1 chain around the main structure. One sprinkler kit has been set up; ran by one Wick 375 pump. This pump is also runs the sprinklers on CC16.

Vegetation/Fuel Inventory

Over-story

- White Spruce**
 Black Spruce
 Mixed
 _____ % Hardwoods
100% Conifer

Average Tree Height

_____ **Spruce 30 ft**
 _____ Hardwood

Understory

- Tall Shrub >6 ft
 Short Shrub <6 ft
 Grass/Forbes
 Moss/Lichens

Canopy Closure

- Closed >50%**
 Open 10-49%

Ladder Fuels

- Yes**
 No

Fuels Description

Terrain

Slope

- 0-25%**
 51-75%
 26-50%
 76-100%

Aspect

- N
 E
 S
 W
 NE
 SE
 SW
 NW
 Flat

Suppression Data

Water Source

Location/Description 5 Mile Clear Creek

Helispot

Location/Description 64 19.578', 146 55.838'

Other Access

Location/Description Jet, or airboat access only from Salcha boat launch. Sacha River to Tanana to 5 MI Clear Creek.

Notes:

Inhabited

Photo included

Sketch of plumbing set up on back



CC16 Site Assessment Survey

Date 7/7/15 Time 12:00

Site Assessor Unawweep WFM

Site Type

- Cabin**
 Allotment
 Camp
 RAWS
 Historical
 Homestead
 Construction
 Archeological
 Communications
 Mining
 Camp
 Trade&Mfg
 Allotment
 T&ESpecies
 Mech.Equip.
 Headquarters
 Other

Quad Name _____ Lat 64° 18.613 TWN/RNG/SEC _____
 Quad _____ Long -146° 52.842 Allotment #6 _____
 Number _____
 Owner John Ellenson Phone 907-488-3801 Permit# _____
 Address 5 Mile Clear Creek

Description of Location

Sixteenth structure on 5 Mile Clear Creek on river right (looking down river).
 1 structure on site.

Fire Management Option (Site Protection Level)

- Limited**
 Modified
 Avoid
 Pending determination

- Full
 Critical
 Non-sensitive

Land Status

- BLM
 NPS
 State
 Trespass
 FWS
 USFS
 Military
 Private
 Native Corporation

Cabin Description

Cabin Construction

- Log**
 Frame
 Other
0 # of outbuildings

Foundation

- Closed
 Open
 Deck
 Other

Roof Type

- Metal**
 Shake
 Composite
 Sod
 Tarp

Condition of Cabin

- Complete structure**
 Walls without roof
 Under construction
 Walls & roof collapsed
 Cabin site, remains

Hazardous Materials

- None
 Empty fuel cans
 Full fuel cans
 Batteries
 Other

Description (outbuildings, docks, machinery, defensible space, etc.)

1 structure on site, accessible by boat. Structure is a finished cabin. Black Spruce has been thinned by 1 chain around the main structure. One sprinkler kit has been set up; ran by one Wick 375 pump which is located at CC15.

Vegetation/Fuel Inventory

Over-story

- White Spruce**
 Black Spruce
 Mixed
 % Hardwoods
100% Conifer

Average Tree Height

Spruce 30 ft
 Hardwood

Understory

- Tall Shrub >6 ft
 Short Shrub <6 ft
 Grass/Forbes
 Moss/Lichens

Canopy Closure

- Closed >50%**
 Open 10-49%

Ladder Fuels

- Yes**
 No

Fuels Description

Terrain

Slope

- 0-25%**
 51-75%
 26-50%
 76-100%

Aspect

- N
 E
 S
 W
 NE
 SE
 SW
 NW
 Flat

Suppression Data

Water Source

Location/Description 5 Mile Clear Creek

Helispot

Location/Description 64 19.578', 146 55.838'

Other Access

Location/Description Jet, or airboat access only from Salcha boat launch. Sacha River to Tanana to 5 MI Clear Creek.

Notes:

- Inhabited
 Photo included
 Sketch of plumbing set up on back



CC17 Site Assessment Survey

Date 7/7/15 Time 12:00

Site Assessor UnawEEP WFM

Site Type

- Cabin**
 Allotment
 Camp
 RAWS
 Historical
 Homestead
 Construction
 Archeological
 Communications
 Mining
 Camp
 Trade&Mfg
 Allotment
 T&ESpecies
 Mech.Equip.
 Headquarters
 Other

Quad Name _____ Lat 64° 18.378 TWN/RNG/SEC _____
 Quad _____ Long -146° 52.519 Allotment #21 _____
 Number _____
 Owner Jim Spence Phone Unknown Permit# _____
 Address 5 Mile Clear Creek

Description of Location

Seventeenth structure on 5 Mile Clear Creek on river left (looking down river).
2 structures on site.

Fire Management Option (Site Protection Level)

- Limited**
 Modified
 Avoid
 Pending determination
 Full
 Critical
 Non-sensitive

Land Status

- BLM
 NPS
 State
 Trespass
 FWS
 USFS
 Military
 Private
 Native Corporation

Cabin Description

- | | | | | |
|---|--|---|---|--|
| Cabin Construction
<input type="checkbox"/> Log
<input checked="" type="checkbox"/> Frame
<input type="checkbox"/> Other
<u>1</u> # of outbuildings | Foundation
<input type="checkbox"/> Closed
<input checked="" type="checkbox"/> Open
<input type="checkbox"/> Deck
<input type="checkbox"/> Other | Roof Type
<input checked="" type="checkbox"/> Metal
<input type="checkbox"/> Shake
<input type="checkbox"/> Composite
<input type="checkbox"/> Sod
<input type="checkbox"/> Tarp | Condition of Cabin
<input checked="" type="checkbox"/> Complete structure
<input type="checkbox"/> Walls without roof
<input type="checkbox"/> Under construction
<input type="checkbox"/> Walls & roof collapsed
<input type="checkbox"/> Cabin site, remains | Hazardous Materials
<input type="checkbox"/> None
<input type="checkbox"/> Empty fuel cans
<input checked="" type="checkbox"/> Full fuel cans
<input type="checkbox"/> Batteries
<input type="checkbox"/> Other |
|---|--|---|---|--|

Description (outbuildings, docks, machinery, defensible space, etc.)

2 total structures on site, accessible by boat at the cable bridge which prevents further travel up creek. Structure is a finished cabin.

Black Spruce has been thinned by 1 chain around the main structure. One sprinkler kit has been set up; ran by one Honda lightweight pump.

Vegetation/Fuel Inventory

- | | | | | |
|---|---|--|--|--|
| Over-story
<input checked="" type="checkbox"/> White Spruce
<input checked="" type="checkbox"/> Black Spruce
<input type="checkbox"/> Mixed
% Hardwoods
<u>100%</u> Conifer | Average Tree Height
<u>Spruce 30 ft</u>
Hardwood | Understory
<input type="checkbox"/> Tall Shrub >6 ft
<input type="checkbox"/> Short Shrub <6 ft
<input checked="" type="checkbox"/> Grass/Forbes
<input checked="" type="checkbox"/> Moss/Lichens | Canopy Closure
<input checked="" type="checkbox"/> Closed >50%
<input type="checkbox"/> Open 10-49% | Ladder Fuels
<input checked="" type="checkbox"/> Yes
<input type="checkbox"/> No |
|---|---|--|--|--|

Fuels Description

Terrain

- Slope**
 0-25%
 51-75%
 26-50%
 76-100%
Aspect
 N
 E
 S
 W
 NE
 SE
 SW
 NW
 Flat

Suppression Data

- Water Source**
 Location/Description 5 Mile Clear Creek
 Helispot
 Location/Description 64 19.578', 146 55.838'
 Other Access
 Location/Description Jet, or airboat access only from Salcha boat launch. Sacha River to Tanana to 5 MI Clear Creek.

Notes:

- Inhabited
 Photo included
 Sketch of plumbing set up on back



CC18 Site Assessment Survey

Date 7/7/15 Time 12:00

Site Assessor Unawep WFM

Site Type

- Cabin**
 Allotment
 Camp
 RAWS
 Historical
 Homestead
 Construction
 Archeological
 Communications
 Mining
 Camp
 Trade&Mfg
 Allotment
 T&ESpecies
 Mech.Equip.
 Headquarters
 Other

Quad Name _____ Lat 64° 18.372 TWN/RNG/SEC _____
 Quad _____ Long -146° 52.449 Allotment #20 _____
 Number _____
 Owner Tim Davis Phone Unknown Permit# _____
 Address 5 Mile Clear Creek

Description of Location

Eighteenth structure on 5 Mile Clear Creek on river left (looking down river).

4 structures on site 2 of which are complete.

Fire Management Option (Site Protection Level)

- Limited
 Modified
 Avoid
 Pending determination
 Full
 Critical
 Non-sensitive

Land Status

- BLM
 NPS
 State
 Trespass
 FWS
 USFS
 Military
 Private
 Native Corporation

Cabin Description

- | | | | | |
|---|--|---|---|--|
| Cabin Construction
<input checked="" type="checkbox"/> <u>Log</u>
<input checked="" type="checkbox"/> <u>Frame</u>
<input type="checkbox"/> Other
<u>3</u> # of outbuildings | Foundation
<input type="checkbox"/> Closed
<input checked="" type="checkbox"/> <u>Open</u>
<input type="checkbox"/> Deck
<input type="checkbox"/> Other | Roof Type
<input checked="" type="checkbox"/> <u>Metal</u>
<input type="checkbox"/> Shake
<input type="checkbox"/> Composite
<input type="checkbox"/> Sod
<input checked="" type="checkbox"/> <u>Tarp</u> | Condition of Cabin
<input checked="" type="checkbox"/> <u>Complete structure</u>
<input checked="" type="checkbox"/> <u>Walls without roof</u>
<input checked="" type="checkbox"/> <u>Under construction</u>
<input type="checkbox"/> Walls & roof collapsed
<input checked="" type="checkbox"/> <u>Cabin site, remains</u> | Hazardous Materials
<input type="checkbox"/> None
<input type="checkbox"/> Empty fuel cans
<input checked="" type="checkbox"/> <u>Full fuel cans</u>
<input checked="" type="checkbox"/> <u>Batteries</u>
<input type="checkbox"/> Other |
|---|--|---|---|--|

Description (outbuildings, docks, machinery, defensible space, etc.)

4 total structures on site, accessible by boat at the cable bridge which prevents further travel up creek. Structure is a finished cabin and shed with an unfinished cabin and outbuilding. Black Spruce has been thinned by 1 chain around the main structure. One sprinkler kit has been set up; ran by one Shindaiwa pump.

Vegetation/Fuel Inventory

- | | | | | |
|---|---|--|--|--|
| Over-story
<input checked="" type="checkbox"/> <u>White Spruce</u>
<input checked="" type="checkbox"/> <u>Black Spruce</u>
<input type="checkbox"/> Mixed
% Hardwoods _____
<u>100%</u> Conifer | Average Tree Height
_____ <u>Spruce 30 ft</u>
_____ Hardwood | Understory
<input type="checkbox"/> Tall Shrub >6 ft
<input type="checkbox"/> Short Shrub <6 ft
<input checked="" type="checkbox"/> <u>Grass/Forbes</u>
<input checked="" type="checkbox"/> <u>Moss/Lichens</u> | Canopy Closure
<input checked="" type="checkbox"/> <u>Closed >50%</u>
<input type="checkbox"/> Open 10-49% | Ladder Fuels
<input checked="" type="checkbox"/> <u>Yes</u>
<input type="checkbox"/> No |
|---|---|--|--|--|

Fuels Description

Terrain

- Slope**
 0-25%
 51-75%
 26-50%
 76-100%
- Aspect**
 N
 E
 S
 W
 NE
 SE
 SW
 NW
 Flat

Suppression Data

- Water Source**
 Location/Description 5 Mile Clear Creek
- Helispot**
 Location/Description 64 19.578', 146 55.838'
- Other Access**
 Location/Description Jet, or airboat access only from Salcha boat launch. Sacha River to Tanana to 5 MI Clear Creek.

Notes:

- Uninhabited
 Photo included
 Sketch of plumbing set up on back



CC19 Site Assessment Survey

Date 7/7/15 Time 12:00

Site Assessor Unawep WFM

Site Type

- Cabin**
 Allotment
 Camp
 RAWS
 Historical
 Homestead
 Construction
 Archeological
 Communications
 Mining
 Camp
 Trade&Mfg
 Allotment
 T&ESpecies
 Mech.Equip.
 Headquarters
 Other

Quad Name _____ Lat 64° 18.453 TWN/RNG/SEC _____
 Quad _____ Long -146° 52.498 Allotment #24 _____
 Number _____
 Owner Dale Starky Phone Unknown Permit# _____
 Address 5 Mile Clear Creek

Description of Location

Nineteenth structure on 5 Mile Clear Creek on river right (looking down river).

3 structures on site.

Fire Management Option (Site Protection Level)

- Limited**
 Modified
 Avoid
 Pending determination
 Full
 Critical
 Non-sensitive

Land Status

- BLM
 NPS
 State
 FWS
 USFS
 Military
 Private
 Native Corporation

Cabin Description

- | | | | | |
|---|--|---|---|--|
| Cabin Construction
<input checked="" type="checkbox"/> Log
<input type="checkbox"/> Frame
<input type="checkbox"/> Other
2# of outbuildings _____ | Foundation
<input checked="" type="checkbox"/> Closed
<input type="checkbox"/> Open
<input type="checkbox"/> Deck
<input type="checkbox"/> Other | Roof Type
<input checked="" type="checkbox"/> Metal
<input type="checkbox"/> Shake
<input type="checkbox"/> Composite
<input type="checkbox"/> Sod
<input type="checkbox"/> Tarp | Condition of Cabin
<input checked="" type="checkbox"/> Complete structure
<input type="checkbox"/> Walls without roof
<input type="checkbox"/> Under construction
<input type="checkbox"/> Walls & roof collapsed
<input type="checkbox"/> Cabin site, remains | Hazardous Materials
<input type="checkbox"/> None
<input type="checkbox"/> Empty fuel cans
<input checked="" type="checkbox"/> Full fuel cans
<input checked="" type="checkbox"/> Batteries
<input type="checkbox"/> Other |
|---|--|---|---|--|

Description (outbuildings, docks, machinery, defensible space, etc.)

3 total structures on site, accessible by boat at the cable bridge which prevents further travel up creek. Structure is a finished two-story cabin with an out house and shed. Black Spruce has been thinned by 1 chain around the main structure. One sprinkler kit has been set up; ran by one Wick 375 pump.

Vegetation/Fuel Inventory

- | | | | | |
|--|---|--|--|--|
| Over-story
<input checked="" type="checkbox"/> White Spruce
<input checked="" type="checkbox"/> Black Spruce
<input type="checkbox"/> Mixed
% Hardwoods _____
100% Conifer | Average Tree Height
_____ Spruce 30 ft
_____ Hardwood | Understory
<input type="checkbox"/> Tall Shrub >6 ft
<input type="checkbox"/> Short Shrub <6 ft
<input checked="" type="checkbox"/> Grass/Forbes
<input checked="" type="checkbox"/> Moss/Lichens | Canopy Closure
<input checked="" type="checkbox"/> Closed >50%
<input type="checkbox"/> Open 10-49% | Ladder Fuels
<input checked="" type="checkbox"/> Yes
<input type="checkbox"/> No |
|--|---|--|--|--|

Fuels Description

Terrain

- Slope**
 0-25%
 51-75%
 26-50%
 76-100%
Aspect
 N
 E
 S
 W
 NE
 SE
 SW
 NW
 Flat

Suppression Data

- Water Source**
 Location/Description 5 Mile Clear Creek
 Helispot
 Location/Description 64 19.578', 146 55.838'
 Other Access
 Location/Description Jet, or airboat access only from Salcha boat launch. Sacha River to Tanana to 5 MI Clear Creek.

Notes:

- Inhabited
 Photo included
 Sketch of plumbing set up on back



CC20 Site Assessment Survey

Date 7/7/15 Time 12:00

Site Assessor UnawEEP WFM

Site Type

- Cabin**
 Allotment
 Camp
 RAWS
 Historical
 Homestead
 Construction
 Archeological
 Communications
 Mining
 Camp
 Trade&Mfg
 Allotment
 T&ESpecies
 Mech.Equip.
 Headquarters
 Other

Quad Name _____ Lat 64° 17.983 TWN/RNG/SEC _____
 Quad _____ Long -146° 51.680 Allotment #52
 Number _____
 Owner Gabe Christman Phone 970-799-3145 Permit# _____
 Address 5 Mile Clear Creek

Description of Location

Twentieth structure on 5 Mile Clear Creek on river right (looking down river) up river from cable bridge. Access via ATV trail from cable bridge through CC18.

3 structures on site. 1 cabin, 1 sauna, one incomplete outhouse.

Fire Management Option (Site Protection Level)

- Limited**
 Modified
 Avoid
 Pending determination
 Full
 Critical
 Non-sensitive

Land Status

- BLM
 NPS
 State
 Trespass
 FWS
 USFS
 Military
 Private
 Native Corporation

Cabin Construction

- Log**
 Frame
 Other
2 # of outbuildings

Foundation

- Closed**
 Open
 Deck
 Other

Roof Type

- Metal**
 Shake
 Composite
 Sod
 Tarp

Cabin Description

Condition of Cabin

- Complete structure**
 Walls without roof
 Under construction
 Walls & roof collapsed
 Cabin site, remains

Hazardous Materials

- None
 Empty fuel cans
 Full fuel cans
 Batteries
 Other

Description (outbuildings, docks, machinery, defensible space, etc.)

3 total structures on site, accessible by ATV trail through CC18 from cable bridge which prevents further travel up creek.

Structure is a finished cabin and sauna with an unfinished outhouse. Black spruce has been thinned by 1 chain around the main structure. Two sprinkler kits have been set up; ran by one Mark III pump.

Over-story

- White Spruce**
 Black Spruce
 Mixed
 _____ % Hardwoods
100% Conifer

Average Tree Height

Spruce 30 ft
 _____ Hardwood

Vegetation/Fuel Inventory

- Understory**
 Tall Shrub >6 ft
 Short Shrub <6 ft
 Grass/Forbes
 Moss/Lichens

Canopy Closure

- Closed >50%**
 Open 10-49%

Ladder Fuels

- Yes**
 No

Fuels Description

Slope

- 0-25%**
 51-75%
 26-50%
 76-100%

Terrain

Aspect

- N
 E
 S
 W
 NE
 SE
 SW
 NW
 Flat

Suppression Data

Water Source

Location/Description 5 Mile Clear Creek

Helispot

Location/Description 64 19.578', 146 55.838'

Other Access

Location/Description Jet, or airboat access only from Salcha boat launch. Sacha River to Tanana to 5 MI Clear Creek.

Notes:

Inhabited

Photo included

Sketch of plumbing set up on back



CC21 Site Assessment Survey

Date 7/7/15 Time 12:00

Site Assessor Unawep WFM

Site Type

- Site type options: Cabin, Allotment, Camp, RAWS, Historical, Homestead, Construction, Archeological, Communications, Mining, Trade&Mfg, T&ESpecies, Mech.Equip, Headquarters, Other

Quad Name, Lat, Long, TWN/RNG/SEC, Quad Number, Owner, Phone, Permit#, Address

Description of Location

Twenty-first structure on 5 Mile Clear Creek on river left (looking down river). Access via continuation of ATV trail from CC20.

1 structure on site.

Fire Management Option (Site Protection Level)

- Fire management options: Limited, Modified, Avoid, Pending determination, Full, Critical, Non-sensitive

Land Status

- Land status options: BLM, FWS, Native Corporation, NPS, USFS, State, Military, Trespass, Private

Cabin Description

- Cabin description options: Cabin Construction, Foundation, Roof Type, Condition of Cabin, Hazardous Materials

Description (outbuildings, docks, machinery, defensible space, etc.)

1 structure on site, accessible by ATV trail from CC20. Structure is an unfinished cabin. Windows have not been installed into cut out walls.

Over-story

- Over-story options: White Spruce, Black Spruce, Mixed, % Hardwoods, 100% Conifer

Average Tree Height

Spruce 40 ft, Hardwood

Vegetation/Fuel Inventory

- Vegetation options: Understory, Tall Shrub >6 ft, Short Shrub <6 ft, Grass/Forbes, Moss/Lichens

Canopy Closure

- Canopy closure options: Closed >50%, Open 10-49%

Ladder Fuels

- Ladder fuels options: Yes, No

Fuels Description

White spruce near structure with large hardwood stands to the North, West, and South.

Terrain

Slope

- Slope options: 0-25%, 51-75%, 26-50%, 76-100%

Aspect

- Aspect options: N, E, S, W, NE, SE, SW, NW, Flat

Suppression Data

- Suppression data options: Water Source, Helispot, Other Access

Notes:

- Uninhabited, Photo included



CC22 Site Assessment Survey

Date 7/7/15 Time 12:00

Site Assessor Unawweep WFM

Site Type

- Cabin** Allotment Camp RAWS Historical Homestead Construction Archeological Communications
 Mining Camp Trade&Mfg Allotment T&ESpecies Mech.Equip. Headquarters Other _____

Quad Name _____ Lat 64 24.173 TWN/RNG/SEC _____
Quad _____ Long -147 03.088 Allotment #51 _____
Number _____
Owner Military Phone 907-361-9318 Permit# _____
Address _____

Description of Location

1 structure on site.

Fire Management Option (Site Protection Level)

- Limited** Full
 Modified Critical
 Avoid Non-sensitive
 Pending determination

Land Status

- BLM NPS State Trespass
 FWS USFS Military **Private**
Native Corporation

Cabin Description

- | | | | | |
|---|--|---|--|--|
| Cabin Construction | Foundation | Roof Type | Condition of Cabin | Hazardous Materials |
| <input type="checkbox"/> Log | <input type="checkbox"/> Closed | <input checked="" type="checkbox"/> Metal | <input checked="" type="checkbox"/> Complete structure | <input type="checkbox"/> None |
| <input checked="" type="checkbox"/> Frame | <input checked="" type="checkbox"/> Open | <input type="checkbox"/> Shake | <input type="checkbox"/> Walls without roof | <input type="checkbox"/> Empty fuel cans |
| <input type="checkbox"/> Other | <input type="checkbox"/> Deck | <input type="checkbox"/> Composite | <input type="checkbox"/> Under construction | <input type="checkbox"/> Full fuel cans |
| _____ # of outbuildings | <input type="checkbox"/> Other | <input type="checkbox"/> Sod | <input type="checkbox"/> Walls & roof collapsed | <input type="checkbox"/> Batteries |
| | | <input type="checkbox"/> Tarp | <input type="checkbox"/> Cabin site, remains | <input type="checkbox"/> Other |

Description (outbuildings, docks, machinery, defensible space, etc.)

1 structure on site, accessible by ATV trail from Tanana River..

Over-story

- White Spruce**
 Black Spruce
 Mixed
_____ % Hardwoods
100% Conifer

Average Tree Height

_____ **Spruce 40 ft**
_____ Hardwood

Vegetation/Fuel Inventory

- Understory**
 Tall Shrub >6 ft
 Short Shrub <6 ft
 Grass/Forbes
 Moss/Lichens

Canopy Closure

- Closed >50%**
 Open 10-49%

Ladder Fuels

- Yes**
 No

Fuels Description

Terrain

Slope

- 0-25%** 51-75% 26-50% 76-100%

Aspect

- N E S W NE SE SW NW **Flat**

Suppression Data

- Water Source**
Location/Description _____
- Helispot**
Location/Description _____
- Other Access**
Location/Description Jet, or airboat access only from Salcha boat launch. Sacha River to Tanana.

Notes:

- Uninhabited Photo included Sketch of plumbing set up on back

